



नेपाल सरकार

राष्ट्रिय पुनर्निर्माण प्राधिकरण

(गुनासो व्यवस्थापन तथा समन्वय शाखा)

सिंहदरबार, काठमाडौं ।

प.सं. : ०७५/७६ (५१६)
च.नं. : २६



फोन नं. ०१-४२००५९९

मिति: २०७५।०४।२८

बिषय: अन्यत्र अर्को बस्नयोग्य घर भएका व्यक्तिहरूको सम्बन्धमा ।

श्री जिल्ला आयोजना कार्यान्वयन इकाई,
(अनुदान व्यवस्थापन तथा स्थानीय पूर्वाधार),
ओखलढुंगा/सिन्धुली/रामेछाप/दोलखा/सिन्धुपाल्चोक/काभ्रेपलाञ्चोक/भक्तपुर/ललितपुर/काठमाडौं/रसुवा/नुवाकोट/
धादिङ्ग/मकवानपुर/गोरखा ।

राष्ट्रिय पुनर्निर्माण प्राधिकरण कार्यकारी समितिको मिति २०७५।०३।०१ को १०७ औं बैठकको निर्णय प्रतिलिपि प्राप्त भएकै होला । उक्त बैठकको निर्णय नं ४ को बुँदा (ड) अनुसार गुनासोकर्ताहरूको अन्यत्र अर्को बस्नयोग्य घर भए नभएको सम्बन्धित गाउँपालिका/नगरपालिकाका प्रमुख प्रशासकीय अधिकृतहरूलाई प्रमाणित गरी पठाउन निर्देशन भएको व्यहोरा अवगतै छ । भूकम्पबाट प्रभावित निजी आवास पुनर्निर्माण अनुदान वितरण कार्यविधि (पहिलो संशोधन), २०७३ को दफा ३ को उपदफा १ खण्ड (ख) मा भूकम्पबाट क्षतिग्रस्त भएको घर बाहेक सोही स्थान वा अन्यत्र बसोबासयोग्य अर्को घर नभएको व्यक्ति वा परिवार मात्र लाभग्राही हुन सक्ने व्यवस्था भएकोले उपरोक्त बमोजिम अन्यत्र अर्को बस्नयोग्य घर (House in Other Place) भएका भनी सूचीमा उल्लेखित व्यक्तिहरूको घर छ वा छैन भनी गाउँपालिका/नगरपालिकाका प्रमुख प्रशासकीय अधिकृतहरूले प्रमाणित गरी पठाउँदा सम्बन्धित व्यक्ति तथा निजको एकाघरको परिवारका सदस्यको नाममा घर भए, नभएको यकिन गरेर मात्र प्रमाणित गर्नुहुन आदेशानुसार अनुरोध गरिन्छ ।

(लालबहादुर बस्नेत)
शाखा अधिकृत



नेपाल सरकार
राष्ट्रिय पुनर्निर्माण प्राधिकरण
केन्द्रीय आयोजना कार्यान्वयन इकाई
(अनुदान व्यवस्थापन तथा स्थानीय पूर्वाधार)

ज्वागल, ललितपुर

प.सं.: २०७५/०७६

मिति: २०७५/४/२७

च.नं.: ६४

श्री जिल्ला आयोजना कार्यान्वयन इकाई,
(अनुदान व्यवस्थापन तथा स्थानीय पूर्वाधार), सिन्धुपाल्चोक, गोरखा, काठमाण्डौ, भक्तपुर, ललितपुर, नुवाकोट,
रसुवा, धादिङ्ग, काभ्रेपलाञ्चोक, ओखलढुङ्गा, सिन्धुली, रामेछाप, मकवानपुर, दोलखा, धनकुटा, संखुवासभा, भोजपुर,
खोटाङ, सोलुखुम्बु, चितवन, कास्की, नवलपरासी, लम्जुङ्ग, तनहुँ, अर्घाखाँची, गुल्मी, पाल्पा, स्याङ्जा, पर्वत, बाग्लुङ्ग
र म्याग्दी ।

श्री महानगरपालिका/उप-महानगरपालिका/नगरपालिका/गाउँ कार्यपालिकाको कार्यालय,
भूकम्प प्रभावित ३१ जिल्लाका सबै ।

विषय : लाभग्राही परिवर्तन सम्बन्धमा ।

उपरोक्त सम्बन्धमा राष्ट्रिय पुनर्निर्माण प्राधिकरण (गुनासो व्यवस्थापन तथा समन्वय शाखा)को पं.सं.०७५।०७६,
च.नं.१४ को पत्रानुसार लाभग्राही परिवर्तन गर्ने सम्बन्धमा तहाँबाट प्रेषित कागजातहरु पुनर्निर्माण सम्बन्धी गुनासो
व्यवस्थापन कार्यविधि, २०७४ बमोजिम भएको नपाइएको हुँदा सो सम्बन्धमा देहाय बमोजिमका (सबै कागजातमा
निवेदकको सम्झौता क्रम नम्बर PA Number अनिवार्य उल्लेख गर्ने) कागजातहरु सक्कलै उपलब्ध गर्नु गराउनु
हुन भनी लेखीआएकोले सोही अनुसार आवश्यक प्रक्रिया पुरा गरी गुनासो विवरण पठाउने व्यवस्था मिलाउनु हुन
अनुरोध छ ।


देहाय :

प्रबलीकरणबाट पुनर्निर्माण लाभग्राहीमा परिवर्तन :

१. वडा सर्जमिन मुचुल्का
२. इन्जिनियरको सिफारिस (निवेदकको छुट्टाछुट्टै)
३. वडास्तरीय गुनासो व्यवस्थापन समितिको निर्णयको प्रतिलिपि
४. गाउँपालिका/नगरपालिकाको सिफारीस

पुनर्निर्माण लाभग्राहीबाट प्रबलीकरण लाभग्राहीमा परिवर्तन

१. इन्जिनियरको सिफारिस (निवेदकको छुट्टाछुट्टै)
२. वडास्तरीय गुनासो व्यवस्थापन समितिको निर्णयको प्रतिलिपि
३. गाउँपालिका/नगरपालिकाको सिफारीस



(नारायण प्रसाद श्रेष्ठ)

आयोजना उप-निर्देशक

बोधार्थ :

श्री राष्ट्रिय पुनर्निर्माण प्राधिकरण,
(गुनासो व्यवस्थापन तथा समन्वय शाखा)

सिंहदरवार, काठमाण्डौ ।

श्री MIS Specialist, सिन्धुपाल्चोक, गोरखा, काठमाण्डौ, भक्तपुर, ललितपुर, नुवाकोट, रसुवा, धादिङ्ग, काभ्रेपलाञ्चोक,
ओखलढुङ्गा, सिन्धुली, रामेछाप, मकवानपुर र दोलखा ।

श्री Focal Person, DLPHU, धनकुटा, संखुवासभा, भोजपुर, खोटाङ, सोलुखुम्बु, चितवन, कास्की, नवलपरासी, लम्जुङ्ग, तनहुँ,
अर्घाखाँची, गुल्मी, पाल्पा, स्याङ्जा, पर्वत, बाग्लुङ्ग र म्याग्दी ।

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS
12995	RV	1024555	285318	1513013	Gorkha	Gandaki Rural Municipality	1	Bam Bahadur Gurung	Bam Bahadur Gurung		Non Beneficiary	Both	Based on previous survey, no severe damage seen in Brick/ block in cement house
13003	RV	1028291	285355	1513085	Gorkha	Gandaki Rural Municipality	1	Chandra Bahadur Bika	Chandra Bahadur Bika		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in Brick/ block in cement house
13004	RV	1028303	282296	15120095	Gorkha	Gandaki Rural Municipality	1	Chiranjibi Shrestha	Sit Kumari Shrestha		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in RC frame (non-engineered) house
13011	RV	1025395	285258	1513080	Gorkha	Gandaki Rural Municipality	1	Ek Maya Gurung	Eak Maya Gurung		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement) with age of house is only 3 year
13022	RV	1028556	285378	1513110	Gorkha	Gandaki Rural Municipality	1	Jeet Bahadur Gurung	Jeet Bahadur Gurung	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13034	RV	1024556	285325	1513014	Gorkha	Gandaki Rural Municipality	1	Nar Bahadur Bishwokarma	Nar Bahadur Bishwarkama		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in Brick/ block in cement house
13057	RV	1028305	285358	1513097	Gorkha	Gandaki Rural Municipality	1	Tej Bahadur Shrestha	Tej Bahadur Shrestha		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (Brick/ block in cement)
13076	RV	1044090	296760	1513218	Gorkha	Gandaki Rural Municipality	2	Deu Bahadur Gurung	Deu Bahadur Gurung		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13106	RV	1028648	296730	1513196	Gorkha	Gandaki Rural Municipality	2	Ram Bahadur Panta	Ram Bahadur Panta		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13175	RV	1046892	291867	1513316	Gorkha	Gandaki Rural Municipality	3	Krishna Prasad Tiwari	Tika Ram Tewari		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (non-engineered))

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS
13198	RV	1046825	291815	1513294	Gorkha	Gandaki Rural Municipality	3	Sitaram Adhikari	Sita Ram Adikari	Roof/Floor Collapse/ Partial Collapse	Non Beneficiary	Legal	House in other place
13241	RV	1053956	291870	1513349	Gorkha	Gandaki Rural Municipality	4	Buddhinarayan Shrestha	Badri Narayan Shrestha		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13248	RV	1053936	291866	151335	Gorkha	Gandaki Rural Municipality	4	Giriraj Panta	Giri Raj Panta		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13331	RV	1105422	294760	1516059	Gorkha	Gandaki Rural Municipality	5	Purna Maya Thapamagar	Purna Maya Thapa Magar		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house
13344	RV	1105455	294583	1516081	Gorkha	Gandaki Rural Municipality	5	Santa Bahadur Sarki	Santa Bahadur Sarki		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (Brick/ block in cement)
13353	RV	1105435	294585	1516178	Gorkha	Gandaki Rural Municipality	5	Til Bahadur Thapa	Til Bahadur Thapa		Non Beneficiary	Both	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13357	RV	1044169	48	1514037	Gorkha	Gandaki Rural Municipality	7	Sarwasati Aryal	Sarwasati Aryal		Non Beneficiary	Legal	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered)) & now only empty ground shown
13364	RV	1044174	54	1514049	Gorkha	Gandaki Rural Municipality	7	Netra Prasad Khanal	Netra Prasad Khanal		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS	
13373	RV	1044163	41	1514026	Gorkha	Gandaki Rural Municipality	7	Bed Maya Magar	Bed Maya Magar			Non Beneficiary	Technical	Different structures shown in previous survey & latestest survey. Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13374	RV	1044188	59	1514333	Gorkha	Gandaki Rural Municipality	7	Gajendra Prasad Regmi	Gajendra Prasad Regmi			Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13386	RV	1044175	55	1514050	Gorkha	Gandaki Rural Municipality	7	Phanindra Khanal	Phanindra Khanal			Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13387	RV	1044194	65	1514343	Gorkha	Gandaki Rural Municipality	7	Raju Regmi	Raju Regmi			Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13403	RV	1044147	25	1514568	Gorkha	Gandaki Rural Municipality	7	Resham Bahadur Gurung	Resham Bahadur Gurung			Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement and RC frame (non-engineered))
13408	RV	1044207	81	1514618	Gorkha	Gandaki Rural Municipality	7	Maya Devi Regmi	Maya Devi Regmi			Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13413	RV	1044156	34	1514017	Gorkha	Gandaki Rural Municipality	7	Beli Gurung	Beli Gurung			Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (non-engineered))

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS
13418	RV	1044155	33	1514014	Gorkha	Gandaki Rural Municipality	7	Bodh Kumari Nepal	Bodh Kumari Nepal		Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (non-engineered))
13438	RV	1040646	286831	1514326	Gorkha	Gandaki Rural Municipality	7	Danda Pani Regmi	Danda Pani Regmi		Non Beneficiary	Both	Based on previous survey, no severe damage seen in house (Brick/ block in cement & RC frame (non-engineered))
13439	RV	1034993	292622	1514566	Gorkha	Gandaki Rural Municipality	7	Darba Singh Rana	Darba Singh Rana		Non Beneficiary	Both	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13441	RV	1040636	292895	1514332	Gorkha	Gandaki Rural Municipality	7	Deb Raj Regmi	Deb Raj Regmi		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13445	RV	1040644	292391	1514603	Gorkha	Gandaki Rural Municipality	7	Dipak Kumar Dallakoti	Dipak Kumar Dallakoti		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13449	RV	1025958	292458	1514365	Gorkha	Gandaki Rural Municipality	7	Ganesh Gurung	Ganesh Gurung	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13454	RV	1040650	286838	1514346	Gorkha	Gandaki Rural Municipality	7	Kamal Bahadur Rana	Kamal Bahadur Rana		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13461	RV	1034966	286948	1514015	Gorkha	Gandaki Rural Municipality	7	Mandira Bhujel	Mandira Bhujel		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (non-engineered))
13466	RV	1040637	292793	1514341	Gorkha	Gandaki Rural Municipality	7	Radha Mohan Regmi	Radha Mohan Regmi		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (RC frame (non-engineered))

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS
13479	RV	1035009	292940	1514558	Gorkha	Gandaki Rural Municipality	7	Sita Kumari Marahatha	Sita Kumari Marahatha		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13482	RV	1040642	292749	1514347	Gorkha	Gandaki Rural Municipality	7	Tara Devi Magar	Tara Devi Magar		Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement and RC frame (non-engineered))
13483	RV	1040653	283018	1514334	Gorkha	Gandaki Rural Municipality	7	Thana Nath Regmi	Thana Nath Regmi		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement and RC frame (non-engineered))
13486	RV	1040645	286836	1514046	Gorkha	Gandaki Rural Municipality	7	Usha Aryal Dawadi	Usha Aryal		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement)
13508	RV	1064484	202	1514473	Gorkha	Gandaki Rural Municipality	8	Bir Bahadur Gurung	Bir Bahadur Gurung		Non Beneficiary	Legal	Based on previous survey, the Super Structure of the house is Brick/ block in cement & RC frame ((non-engineered))
13515	RV	1044211	87	1514625	Gorkha	Gandaki Rural Municipality	8	Padam Bahadur Sunar	Padam Bahadur Sunar	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13532	RV	1064411	153	1514247	Gorkha	Gandaki Rural Municipality	8	Tara Bahadur Thapa	Tara Bahadur Thapa	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13550	RV	1064464	191	1514454	Gorkha	Gandaki Rural Municipality	8	Lal Bahadur Bishural	Lal Bahadur Bishural		Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (engineered))
13562	RV	1064404	150	1514240	Gorkha	Gandaki Rural Municipality	8	Gam Bahadur Gurung	Gam Bahadur Gurung	Out-of-Plane-Failure of Walls carrying floor/roof	Non Beneficiary	Legal	House in other place
13602	RV	1064451	181	1514089	Gorkha	Gandaki Rural Municipality	8	Ganga Ram Shrestha	Ganga Ram Shrestha	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place

Name : Gandaki

NRA Meeting Date : 2075/03/20

NRA Meeting No : 109

SN	RS_RV	HO_ID	GID	SLIP_NO	District	GP/NP	WARD	GRIEVANT_NAME	HOUSE_OWNER_NAME	MAJOR_DAMAGE	ECOMMENDATIO	REASON	REMARKS
13603	RV	1064455	184	1514094	Gorkha	Gandaki Rural Municipality	8	Mahar Mali Miya	Mahar Mali Miya		Non Beneficiary	Legal	Based on previous survey, no severe damage seen in another house (Brick/ block in cement & RC frame (engineered))
13629	RV	1034978	289556	1514399	Gorkha	Gandaki Rural Municipality	8	Gyandra Bdr Karki	Gyanendra Bahadur Karki		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (RC frame (non-engineered))
13635	RV	1064423	287544	1514059	Gorkha	Gandaki Rural Municipality	8	Jeete Majhi	Jeete Majhi		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in house (Brick/ block in cement
13640	RV	1025924	294158	1514641	Gorkha	Gandaki Rural Municipality	8	Kamal Bahadur Gurung	Kamal Bahadur Gurung	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13645	RV	1025964	289540	1514629	Gorkha	Gandaki Rural Municipality	8	Lalumaya Magar	Lalu Maya Magar	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13653	RV	1034958	283983	1514592	Gorkha	Gandaki Rural Municipality	8	Manju Regmi	Manju Regmi		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (RC frame (engineered))
13659	RV	1043302	292955	1514303	Gorkha	Gandaki Rural Municipality	8	Prem Bdr Sunar	Prem Bahadur Sunar		Non Beneficiary	Both	Based on previous survey, no severe damage seen in another house (Brick/ block in cement)
13662	RV	1035003	293029	1514400	Gorkha	Gandaki Rural Municipality	8	Ramanta Regmi	Ramakant Regmi	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13669	RV	1025955	292592	1514379	Gorkha	Gandaki Rural Municipality	8	Santa Kumari Shrestha	Santa Kumari Shrestha	Collapse or Partial Collapse	Non Beneficiary	Legal	House in other place
13680	RV	1034964	286828	1514589	Gorkha	Gandaki Rural Municipality	8	Yam Prasad Regmi	Yam Prasad Regmi		Non Beneficiary	Technical	Based on previous survey, no severe damage seen in another house (Brick/ block in cement)